

#### **MATERIAL SAFETY DATA SHEET**

**Version:** 1.0 **Date:** 03 May 2023 **Page:** 1 of 5

## 1.- IDENTIFICATION OF PRODUCT AND COMPANY

1.1 Product identification: WS2/WR2 TUNGSTEN ELECTRODE

1.2 Identified pertinent uses of the substance or mixture and uses that are advised against: Arc welding

Classification(s): EN ISO 6848 WS2/WR2

**1.3 Supplier's details:** Chaves Bilbao S.L.,

C/Bizkargi, 6 Pol. Ind. Sarrikola E-48195 LARRABETZU Bizkaia Tel. +34 94 412 34 56 www.chavesbao.com

**1.4 Emergency telephone** number:

Toxicology Information Service

Telephone: Spain: +34 91 562 04 20 (24/7/365)

Other: National support - Poison Centres (europa.eu)

## 2.- IDENTIFICATION OF HAZARDS

**2.1 Product classification:** 1A carcinogenic, H350i (can cause cancer through inhalation) according to

Regulation EC No. 1272/2008

2.2 Label items:

Regulation (EC) No. 1272/2008 label

Directive 67/548/EEC label

GHS08 Hazardous to health

H: 350i Can cause cancer through inhalation

P: Precautionary advice

101 If you need medical advice, keep the packaging or label to hand.

102 Keep out of the reach of children 201 Request special instructions before use

202 Do not handle the substance before having read and understood all the safety instructions

270 Do not eat, drink or smoke during use

281 Use the obligatory personal protective equipment

308+313 In the event of evident or presumed exposure: check with a doctor

405 Keep locked away

501 Dispose of the container/recipient

T: Toxic

R Phrases: 49 Can cause cancer through inhalation

S Phrases:

1/2 Keep locked away and out of the reach of children

7 Keep the recipient tightly closed

13 Keep away from food, drink and animal feed 20/21 Do not eat, drink or smoke during use 23 Do not breathe in gas/fumes/vapour/aerosols

36/37/39 Use appropriate protective clothing: gloves and eye/face protection 45 In case of accident or discomfort, see a doctor immediately (if possible,

show them the label)

60 Dispose of the product and its recipient as hazardous waste

2.3 Other hazards:

N/A



#### **MATERIAL SAFETY DATA SHEET**

Version: 1.0 Date: 03 May 2023 Page: 2 of 5

## 3.- COMPOSITION

## 3.2 Tungsten alloys:

SUBSTANCE	CAS No.	Concentration	Clas. EC 1272/2008	Clas. 67/548/EEC
Tungsten	7440-33-7	> 95%		
Lanthanite	1312-81-8	1-4%		
Other oxides		< 5%		

## 4.- FIRST AID

## 4.1 Description of first aid

In case of accident or a feeling of discomfort, immediately seek medical advice (show the material safety data sheet if possible). Immediately improve contaminated clothing.

Provide fresh air and keep the person warm and at rest. Request immediate medical help. Inhalation

Wash immediately with abundant water and soap. Contact with

the skin

Rinse immediately with abundant water for 10 to 15 minutes, holding the eyelashes back. Request medical Contact with

attention if the problem persists. the eyes

Immediately clean the mouth and drink large quantities of water. Request medical attention if the problem Ingestion

persists.

#### 4.2 Main symptoms and acute and delayed effects:

No specific symptoms. Can cause cancer through inhalation.

## 4.3 Indication of all medical assistance and special treatments that must be provided immediately.

No special measures are required. Treat the symptoms.

#### **5.- FIRE FIGHTING MEASURES**

The extinguishing measures must be chosen based on the surrounding area. The **5.1 Extinguishing means:** 

product is not combustible in itself. Appropriate means: pulverised water, high-

power jet, carbon dioxide, foam, dry extinguishing powder. Radioactive materials (alpha emitters).

5.2 Specific hazards arising

from the substance or mixture:

Use personal respiration devices. Collect the extinguishing water separately to avoid drainage into the rainwater or surface water collection system.

**5.3 Recommendations for fire** fighting personnel:

## 6.- MEASURES IN THE EVENT OF ACCIDENTAL SPILLAGE

6.1 Personal precautions, personal protective equipment and emergency procedures:

See section 8.

6.2 Precautions in relation to

See section 13.

the environment:

6.3 Methods and means of contention and cleaning:

N.A.

**6.4 Reference to other sections:** See section 8/13.



#### **MATERIAL SAFETY DATA SHEET**

**Version:** 1.0 **Date:** 03 May 2023 **Page:** 3 of 5

## 7.- HANDLING AND STORAGE

7.1 Precautions for safe handling:

Ensure that employees know the risks of intoxication. This product must only be used by people over the age of 18 who have been sufficiently informed on its hazardous nature and the need to take safety precautions.

7.2 Safe storage conditions, including possible incompatibilities:

Keep in the original container. Keep containers tightly closed. Restrict access to storage areas. Observe the permitted limits. Store away from food, drink and animal feed.

**7.3 Specific end uses:** Arc welding

# 8.- EXPOSURE CONTROLS/PERSONAL PROTECTION

# 8.1 Control parameters:

Do not allow exposure above the exposure limit values:

Substance:	CAS-No.:	Source:	Occupational exposure limit:	Peak exposure limit:
Tungsten		TRGS 900 (General dust limit 01/06)	3mg/m³ A or 10mg/m³ E	2(II)
Lanthanite		TRGS 900 (General dust limit 01/06)	3mg/m³ A or 10mg/m³ E	2(II)
Other oxides		TRGS 900 (General dust limit 01/06)	3mg/m³ A or 10mg/m³ E	2(II)

Ensure sufficient ventilation and occasional aspiration in critical areas. The technical measures and application of appropriate work methods are prioritised over the use of personal protective equipment. If a radiation dose of over 1mSv/a is foreseen, a control area must be created. Do not eat, drink or smoke in the workplace. Wash hands in breaks and upon finishing work. Apply skincare products after the work. Wash work clothing before reuse.

# 8.2 Exposure controls:

Personal protective equipment: Use a mask with ventilation when working or welding in reduced spaces, or where the ventilation is not sufficient to keep the exposure values within the safety limits. Use appropriate protective equipment such as a combination filter (DIN EN 141). Use certified protective gloves (DIN EN 374) and airtight protection goggles. To protect yourself from direct contact with the skin, it is essential to use additional protective clothing on top of normal work clothing. Only use appropriate, comfortable, clean clothing. Barrier creams must not be used as a substitute for protective clothing.

## 9.- PHYSICAL AND CHEMICAL PROPERTIES

#### 9.1 Information on basic physical and chemical properties:

Appearance: Solid, metal Colour: dark grey Density: 18.3-19.3g/cm<sup>3</sup> Melting point: 3390-3430°C Boiling point: 5660-5900°C



## **MATERIAL SAFETY DATA SHEET**

Version: 1.0 Date: 03 May 2023 Page: 4 of 5

## 10.- STABILITY AND REACTIVITY

Does not react dangerously with other substances under normal conditions. 10.1 Reactivity:

Stable product under normal conditions. 10.2 Chemical stability:

Formation of metal oxides with atmospheric oxygen. 10.3 Possibility of

dangerous reactions:

**10.4 Conditions that must** 

be avoided:

10.5 Incompatible materials:

Oxidising agents.

Toxic metal oxide fumes. **10.6 Hazardous** 

decomposition products:

# 11.- TOXICOLOGICAL INFORMATION

## 11.1 Information on the toxicological effects

Acute toxicity	N.A.
Chronic toxicity	No specific symptoms observed in laboratory animals.

This product is only suitable for manual welding procedures.

## 11.2 Irritation

Irritating effect on the skin	Non-irritating.
Irritating effect in the eyes	Non-irritating.
Irritating effect on the digestive tract	Non-irritating.
Corrosiveness	Non-corrosive.

## 11.3 Awareness

Awareness	N.A.	
11.4 Toxicity due to repeated doses		
Toxicity	Danger of accumulative effects.	

## 12.- ECOLOGICAL INFORMATION

## 12.1 Ecological toxicity

Exotoxicity	N.A.
Persistence and biodegradability	The methods to determine biodegradability do not apply to inorganic substances.
Bioaccumulative potential	N.A.
Mobility in the ground	No.
PBTs and PvBs	This criterion is not applicable.



#### **MATERIAL SAFETY DATA SHEET**

**Version:** 1.0 **Date:** 03 May 2023 **Page:** 5 of 5

## 13.- CONSIDERATIONS IN RELATION TO DISPOSAL

#### 13.1 Methods for the treatment of waste:

Dispose of the product and its packaging according to the applicable national or regional regulations. Clean packaging must be recycled. Manage contaminated packaging in the same way as the substance.

Do not tip down drains or dispose of in aquatic environments. Do not allow to enter the soil/subsoil.

## 14.- INFORMATION IN RELATION TO TRANSPORT

No international regulations or restrictions apply.

## 15.- REGULATORY INFORMATION

#### 15.1 Labelling

Special mixture labelling: only for professional users.

## 15.2 Specific regulation for health, safety and environment

#### **European Union**

DIRECTIVE 1999/13/EC on the limitation of volatile organic compound emissions due to the use of organic	No
solvents in certain activities and installations	
REGULATION 2037/2000 on substances that deplete the ozone layer.	No
REGULATION 689/2008 on the importation and exportation of hazardous chemical products	No
REGULATION 648/2004 on detergents	No
REGULATION 1907/2006 on the registration, evaluation, authorisation and restriction of chemical substances	No
and preparations. Restrictions of title VIII	

## **16.- OTHER INFORMATION**

The information on this Material Safety Data Sheet is based on the technical data held by Chaves Bilbao S.L. and which it believes to be reliable. Given that the conditions of use are out of our control, we take no responsibility in relation to the use made of this information, nor do we guarantee this in any way neither implicitly nor explicitly. In the event of the mixing or processing of the product, this information shall cease to be necessarily valid. For more information, please contact Chaves Bilbao S.L.